



THE WALLS

ARCHITECTURE | URBAN DESIGN | ENGINEERING DRAWINGS | INTERIORS

BUILDING SAFETY CERTIFICATE

This is to certify that, the school building of Vidya Prakash Sangh, Sundargarh, Odisha which has been leased out to the Pallottine Educational Society for a period of 99 years (leaser document no: **10861602118** dated on **17/11/2016**) stands over **plot no - 1/891, 19/892, 20/892, 1/1023, 1/1025, Khata No- 90/121, Mouza Kumudapali, District - Jharsuguda, State- Odisha**, is visited by me and it has been checked that is structurally fit and earthquake proof and it is **"SAFE"** for living human habitant.

Ar. Sakti Ranjan Surja

Ar. Sakti Ranjan Surja
CA/2020/120487

Signature of the Registered Architect
with registration No.

INDUSTRIAL ESTATE, SARBERNA, JHARSUGUDA, ODISHA – 768204. MOBILE no. +91 8249002707,
+91 8249799689



DEPARTMENT OF CIVIL ENGINEERING JHARSUGUDAENGINEERING SCHOOL (A Govt. of Odisha Polytechnic)

Requisition Made Vide letter: NO: NIL

Dated: -16.12.2023

By St. Vincent Pallotti School Kumudapalli, Purna, Jharsuguda


Work Reference:- Testing of SBC Value for Building Safety Certificate of St. Vincent Pallotti School, Kumudapali, Purna, Jharsuguda.


TEST REPORT FOR S.B.C

| Sl. No. | Sample Reference | Date of Sample Collection | S.B.C in T/ m ² | D.F.S. in % |
|---------|------------------|---------------------------|----------------------------|-------------|
| 1 | Sample-1 | 21.12.2023 | 17.20 | 6.0 |
| 2 | Sample-2 | 21.12.2023 | 16.39 | 6.5 |
| 3 | Sample-3 | 21.12.2023 | 18.82 | 7.5 |
| 4 | Sample-4 | 21.12.2023 | 24.61 | 8.5 |

*N.B. :- The test reports pertain to the tests conducted in the laboratory as per the supplied/ Collected samples only.


82/01/24
Technician (C)
Material Testing


Lecturer (Civil)
Jharsuguda Engineering School
Jharsuguda


Sr. Lecturer-Com. HOD (Civil)
Jharsuguda Engineering School
Jharsuguda